

#9

COMPLETE

Collector: Web Link 1 (Web Link)
Started: Friday, January 17, 2025 10:37:07 AM
Last Modified: Friday, January 17, 2025 10:41:38 AM
Time Spent: 00:04:30
IP Address: 160.227.129.139

Page 1: Facilities Request Form

Q1

Contact Person:

Name	Ignacio Castaneda Garcia
Email Address	ignacio.garcia@gcccd.edu

Q2

Department:

Automotive and Electronics

Q3

Title of Request:

Cover for Outside Hoist Area

Q4

Location of Request:

K building outside area near outdoor hoist

Q5

Description of Request:When making your request, please be as specific as possible and include information such as make, model, manufacturer, color, quantity, etc.

The outside lift area needs to be covered. A roof needs to be installed from wall to wall to enclose the outdoor area better.

Q6

Estimated Cost:

We need facilities to help with this estimate.

Q7 Respondent skipped this question

Please attach quote, if available

Q8 **Operations Cost,**
Total Cost of Ownership:check all that apply **Maintenance Cost**

Q9
Please explain your plan to maintain this request:

No maintenance needed.

Q10 **Health/Safety/Security Issues,**
Justification of Request:Please select the applicable **Growth of department/work area,**
criteria below and provide the details how the criteria relate **Demonstrate need for continuous quality improvement**
to your request. **of department/work area**

Provided details::

The outdoor lift area floods when it rains. This causes very large puddles in the lift area and also directs water into the laboratory. The water in the laboratory then can go into the dynamometer which is a heavy duty electrical system the state referee uses daily. This is a huge safety issue and will also make sure rain water does not enter the storm drains. This will also allow us to uncover the outside drain which will help with the flooding. Covering this area will give the department another usable hoist for laboratory instruction.
