

#7

**COMPLETE**

**Collector:** Web Link 1 (Web Link)  
**Started:** Friday, January 17, 2025 10:16:29 AM  
**Last Modified:** Friday, January 17, 2025 10:29:57 AM  
**Time Spent:** 00:13:27  
**IP Address:** 160.227.129.139

---

Page 1: Facilities Request Form

**Q1**

Contact Person:

Name	<b>Ignacio Castaneda Garcia</b>
Email Address	<b>ignacio.garcia@gcccd.edu</b>

---

**Q2**

Department:

Automotive and Electronics

---

**Q3**

Title of Request:

K Building Drains

---

**Q4**

Location of Request:

K Building Laboratory Bays. East and West.

---

**Q5**

Description of Request:When making your request, please be as specific as possible and include information such as make, model, manufacturer, color, quantity, etc.

Remove drain covers.

---

**Q6**

Estimated Cost:

0 dollars to remove the covers. I don't know the cost if there is another route.

---

**Q7** Respondent skipped this question

Please attach quote, if available

---

**Q8** Operations Cost,  
Total Cost of Ownership:check all that apply Maintenance Cost

---

**Q9**  
Please explain your plan to maintain this request:

No maintenance needed.

---

**Q10** Health/Safety/Security Issues,

Justification of Request:Please select the applicable criteria below and provide the details how the criteria relate to your request.

Provided details::

Drains were covered in the automotive lab area initially without notice. Our drains go to a specific clarifier meant for any accidental spillage. With the drains cover the present a safety hazard to our students. We can no longer roll jacks, lifts, or other equipment over the covers. If students do, the equipment can easily fall over and hurt someone. The covers also form large puddles in the middle of the bay that presents a safety hazard to our staff and students. They also are an unpleasant sight. Other department had covers installed, but were able to get them removed.

---