

#8

COMPLETE

Collector: Web Link 1 (Web Link)
Started: Friday, January 17, 2025 10:30:20 AM
Last Modified: Friday, January 17, 2025 10:36:53 AM
Time Spent: 00:06:33
IP Address: 160.227.129.139

Page 1: Facilities Request Form

Q1

Contact Person:

Name	Ignacio Castaneda Garcia
Email Address	ignacio.garcia@gcccd.edu

Q2

Department:

Automotive and Electronics

Q3

Title of Request:

Gate Operator Replacement for K Building

Q4

Location of Request:

K Building towards south west of compound.

Q5

Description of Request:When making your request, please be as specific as possible and include information such as make, model, manufacturer, color, quantity, etc.

The sliding gate operator unit needs to be replaced. See provided quote for exact information.

Q6

Estimated Cost:

25,000

Q7

Please attach quote, if available

Cuyamaca%20College%20Slide%20Operator%20Customer%20Gate%20Quote.pdf (391.9KB)

Q8

Total Cost of Ownership:check all that apply

**Replacement (Life Cycle),
Operations Cost,
Maintenance Cost**

Q9

Please explain your plan to maintain this request:

Constant monitoring of vehicle operation and service intervals.

Q10

Justification of Request:Please select the applicable criteria below and provide the details how the criteria relate to your request.

**Health/Safety/Security Issues,
Demonstrate need for continuous quality improvement
of department/work area**

,
Provided details::
We need to have the gate fixed properly. There are hundred thousands of dollars worth of equipment and vehicles in the shop area that need to be secured. We have sent multiple requests. We have had multiple repair companies come out to service the gate. They have recommended replacing the operator unit since it is over 20 years old and parts are obsolete. The gate is very heavy. Staff has to manually open and close it and someone can get hurt from this.
